	Project	Title: F	Rotherha	m Cremator	ium & Cemetery	TP01			
clancy			Project	Numbe	er: 10/140	68	Client: TCMG	Sheet 1 Of 1	
	GL (m/	AOD):			N Coord: 0	E Coord: 0	E Coord: 0		
Date: 22/08/2	Method: JCB				Logged By: DH Scale: 1:50				
Depth (m)	Туре	Test Resul	t	Level	Legend	Depth (m)	Description	1	Water
2.10	ES				**************************************	0.20 0.80 1.00 2.00 2.10 2.30 	leaves and wood with (compost matter)  Yellowish grey complete recovered as very stiff \$	k brown decaying organic matter, fragments of plastic and metal. ely weathered banded SILTSTONE SILT with sandy partings.	
				:  -  -		10.00			
KEY D - Disturbed Sample B - Bulk Sample W - Water Sample V - Hand Shear Vane kPa  V - Groundwater Strike V - Groundwater Level							REMARKS No Groundwater Encountered Trial pit backfilled with arisings.		